## Work Order ID 100037

April 17, 2013 7:47:32 AM

Page 1

Item ID:

D3186-4

Accept

Setup Start

**Revision ID:** 

Item Name:

Spacepod Door, RH

**Start Date:** 

4/17/13

Start Qty: 1.00

Req'd Qty: 1.00

**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

Required Date: 5/10/13

Date:  $\frac{13}{04}$  Tooling:

Date:

Run

QC:

Date:

Secretary 197

a anytin

Ser Up/

SPC (Y/N):

100140

your Plan

Accept

Reject

ĭьsp.

Work Center ID Draw Nbr

Descripada

Run Hours

Code Qty isoject. Qty Number

Stamp

D3186

Rev E

100 \*100\*

Small Fab

**Revision Nbr** 

Small Fab

Small Fab

Memo

0.00

0.00

1-Trim door to fit spacepod before drill holes and cut out slots for latch as per

dwg D3186 (D3186-4 detail)

Date:

110

QC5- Inspect part completeness to step on W/O

0.00

Memo


0.00

Quality Control

Identify as per dwg & Stock Location:

\*120\*

Memo



120

Packaging Packaging

DQA: \_\_\_\_Date: \_\_\_\_

NCR: Ye	es / No				WORK ORDER NON-O	CONFOR	MANCE / UP	DATE			
	, 								QA Closed:	Date:	
Work Ordei	r: 10	9 <b>00</b> 3	フ		DISPOSITION			AGAINST DE	PARTMENT	PROCESS	
Part No	o	)3186			Rework Scrap Use-as-is Work Order Update	Ther	Skid-tube  Machining  moforming  Large Fab	Crosstube Small Fab Finishing Composite	Water Jet Engineering Prod. Eng. Coor. Quality Rec/Store/Packaging Other Supplier		
Root				Descri	ption of work order update	Initial	Ac	tion	Sign &		
Cause	Date	Step	Qty	(	or Non-conformance	Chief Eng	Desc	ription	Date	Verification	QC Inspector
Ooc/Data Equip/Tooling Operator Waterial Setup Other Process Supplier Training	1309.11	100	0	Prim Dama aveas		B correct	Scuss of entire de Dupent H	t reprime on with igh build prim	Hd 13-9-18	13.04.11	m/m/ 13.09.16
Unapproved			1	<u> </u>	F	AULT CAT	EGORY		<u> </u>		
Landin	g Gear				General		( 4)3	1 "1			
- - - - - - - - - - - - - - - - - - -	Bending Centre No Cracks Crushed/ Cuffs Heat Trea Inspectio Ripples in Torque W	Crimped at n Strip in 1 Bend Vaves in I	I Tube Extrusio		Bend BOM/Route Broken/Damaged Burrs Contamination Countersink Cut Too Short Drill Holes Drawing Finish	Instruction Maint Mislat Misrea Offset Out of	tion Incomplete ctions Incomplete/ cenance peled ad	'Unclear	Ovalized Over/Under Part Incorre Part Lost/Mi Part Moved Positioned V Power Loss/	ssing Vrong	Pressure/Forced Temperature/Cure Weld Wrong Stock Pulled Other
F	Wave/Tw				Folio	<b></b>	le Dimensions				

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

0.00

Memo

Quality Control

W (3-09-17

		DQA:	Date:	
NCR: Yes / No	WORK ORDER NON-CONFORMANCE / UPDATE			
·	·	OA Clasadi	Date	•

											QA Closed:	Date.		
Work Orde	er:					DISPOSITION				AGAINST D	EPARTMENT	/PROCESS		
Part N						Rework Scrap		Skid-tube Crosstube Machining Small Fab Thermoforming Finishing			<del></del> -	Water Jet d. Eng. Coor.	Engineering Quality	
NCR 1	No					Use-as-is Work Order Update			noforming Large Fab	Finishing Composite	T			
Root		•			Descri	iption of work order update		nitial	A	ction	Sign &			
Cause		Date	Step	Qty		or Non-conformance	Ch	ief Eng	Des	cription	Date	Verification	QC inspector	
Doc/Data						•			,					
Equip/Tooling												1		
Operator	Ш													
Material														
Setup	Ш													
Other	Ш										ĺ			
Process	Ш									*				
Supplier	Ш													
Training	Ш													
Unapproved										·				
							AUL	T CATE	GORY					
Landi	_				_	General	<u></u>	ا ما	1 575+1 <i>3</i>	cagr.	<b>-</b>		¬₀	
	-	ending			<b> </b> _	Bend 100 Miles	-	1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Lags.	Ovalized	<u> </u>	Pressure/Forced	
	_		ot Concer	ntric to	o/s	BOM/Route	-	Hardwa		-	Over/Under	}	Temperature/Cure	
	-	racks			<u> </u>	Broken/Damaged		1	ion incomplete	<u></u>	Part Incorre	<del>-</del>	Weld	
			Crimped.		<u> </u>	Burrs		4	ions Incomplete	/Unclear	Part Lost/M		Wrong Stock Pulled	
	-	uffs _			<u> </u>	Contamination	<u> </u>	Mainte		-	Part Moved			
	<b>—</b>	eat Trea			<u> </u>	Countersink	<u> </u>	Mislabe		}-	Positioned		7044	
	_	-	n Strip in	Tube	<u> </u>	Cut Too Short	-	Misread	d	L	Power Loss,	Surge	Other	
	-	ipples in			ļ.  -	Drill Holes	-	Offset	i. Odganija					
		•	/aves in E		n  -	Drawing	-	4	Calibration					
		_	equence		-	Finish	-	•	Sequence					
	I IV	Vave/Tw	ist in Tub	ne	1	Folio		1Outside	Dimensions					

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

April 17, 2013 7:47:31 AM

Work Order ID:

100037

Parent Item:

D3186-4

Parent Item Name:

Spacepod Door, RH

**Start Date:** 4/17/13

Required Date: 5/10/13

Start Qty: 1.00

Required Qty: 1.00

Comments:

IPP Rev:A New Issue 07-01-11 EC

IPP rev.B

revD 07.03.07 ec

IPP Rev:C 10-08-11 added trim

	door before drilling	g DD verf:EC												
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status	
D3186-2M SPACEPOD DOOR RH		Manufactured	No			100	Each	1.0000	1	1	were Managements do			
				<u>Location</u> CA		<u>Luc Oty</u> 1	<u>Lo</u>	<u>c Cούε</u>	B	LDD	3 <i>8</i>		Je2 10	(

75463


DQA:	_ Date:	

NCR: Yes / No

## WORK ORDER NON-CONFORMANCE / UPDATE

			4775				20.00	color and a second	QA Closed:	Date:	
Work Orde	r:				DISPOSITION			AGAINST DE	PARTMENT,	/PROCESS	
Part No	<del></del>	. D			Rework Scrap Use-as-is	I	Skid-tube Machining moforming	Crosstube Small Fab Finishing	4	Water Jet d. Eng. Coor. re/Packaging	Engineering Quality Other
NCR N	0				Work Order Update		Large Fab	Composite	,	Supplier	
Root	,	1		Descr	iption of work order update	Initial	Ad	ction	Sign &		, in the second
Cause	Date	Step	Qty		or Non-conformance	Chief Eng	Desc	cription	Date	Verification	QC Inspector
Doc/Data Equip/Tooling Operator Material Setup Other Process Supplier Training Unapproved			Q., y		or non-comormanes						
onapproved 1		<u> </u>	il		F	AULT CATE	GORY		L	<u> </u>	1
Landin	g Gear	12	:		General		4 10 10		· · · · · · · · · · · · · · · · · · ·	· In.	ş
1	Bending Centre No		ntric to (	D/S	Bend BOM/Route Broken/Damaged	Grain Hardw Inspec	are tion Incomplete		Ovalized Over/Under Part Incorre	tolerance	Pressure/Forced Temperature/Cure Weld
	Crushed/0	Crimped.			Burrs	Instruc	tions Incomplete	/Unclear	Part Lost/M	issing	Wrong Stock Pulled
	Cuffs				Contamination	Maint	enance		Part Moved		
	Heat Trea	it			Countersink	Mislab	eled		Positioned V		7
	Inspection	n Strip in	Tube		Cut Too Short	Misrea	d		Power Loss/	'Surge	Other
	Ripples in	Bend			Drill Holes	Offset					
Γ	Torque W	/aves in E	Extrusion	1 [	Drawing	Out of	Calibration				
Γ	Turning S	equence			Finish	Out of	Sequence				
Γ	Wave/Tw	ist in Tub	oe		Folio	Outsid	e Dimensions				

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G



		DQA:	Date:	
	•			
NCR· Ves / No	WORK ORDER NON-CONFORMANCE / UPDATE			


NCR: Y	Yes ,	/ No				WORK ORDER NON	-COi	NEORI	VIAINCE / UP	DATE	QA Closed:	Date	:
Work Orde	or:			· 5	to the state of th	DISPOSITION				AGAINST DE	PARTMENT,	/PROCESS	
Part N	 No					Rework Scrap Use-as-is Work Order Update			Skid-tube Machining noforming Large Fab	Crosstube Small Fab Finishing Composite	Pro Rec/Sto	Engineering Quality Other	
Root					Descri	ption of work order update		Initial	Ac	tion	Sign &		, , , , , , , , , , , , , , , , , , ,
Cause		Date	Step	Qty	(	or Non-conformance	Ct	nief Eng	Desc	ription	Date	Verification	QC Inspector
Doc/Data Equip/Tooling Operator Material Setup Other Process Supplier Training Unapproved													
							FAUI	T CATE	GORY	· .			
Landi	B C C C C H Ir	ending entre No racks rushed/G uffs eat Trea aspection ipples in	n Strip in	Tube		General Bend BOM/Route Broken/Damaged Burrs Contamination Countersink Cut Too Short Drill Holes Drawing		Instruct Mainte Mislabe Misread Offset	ion Incomplete tions Incomplete/ enance eled	/Unclear	Ovalized Over/Under Part Incorre Part Lost/M Part Moved Positioned V	ct issing Wrong	Pressure/Forced Temperature/Cure Weld Wrong Stock Pulled  Other
	T	urning S	equence			Finish		_Out of:	Sequence				

Outside Dimensions

Wave/Twist in Tube

Folio


H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G



			DQA:	Date:
NCR: Yes / No	WORK ORDER NON-CONFORMANCE / UF	PDATE		

											QA Closed:	Date:	
Work Orde	er:				1	DIS	POSITION			AGAINST DE	PARTMENT	/PROCESS	
Part N	No					Work (	Rework Scrap Use-as-is Order Update	The	Skid-tube  Machining rmoforming  Large Fab	Crosstube Small Fab Finishing Composite	-	Water Jet d. Eng. Coor. re/Packaging Supplier	Engineering Quality Other
Root					Descr	iption of work	order update	Initial	Δ	Action	Sign &		
Cause	D	ate	Step	Qty		or Non-confo	rmance	Chief Er	g Des	scription	Date	Verification	QC Inspector
Doc/Data Equip/Tooling Operator Material													
Setup Other													
Process Supplier Training				·									
Unapproved								<u> </u>			<u> </u>		
								AULT CA	regory				
Làndi	$\boldsymbol{\vdash}$	ding	: Concer	ntric to	o/s	Ger Bend BOM/Route	neral	Grain Hard			Ovalized Over/Under	tolerance	Pressure/Forced Temperature/Cure
	Crad	cks				_Broken/Dan	naged	Inspe	ction Incomplete		Part Incorre	ct	Weld
	Crus	shed/Cr	rimped.			Burrs		Instr	ictions Incomplete	e/Unclear	Part Lost/M	issing	Wrong Stock Pulled
	Cuff	s				Contamination	on	Mair	ntenance		Part Moved		
	Hea	t Treat			L	Countersink		Misla	beled		Positioned '	Wrong	<del></del>
	Insp	ection	Strip in	Tube		Cut Too Shor	t	Misr			Power Loss	/Surge	Other
	Ripples in Bend Drill Holes						Offse						
	Tord	que Wa	ives in E	xtrusio	n _	Drawing		Out	of Calibration				
Turning Sequence Finish						Out of Sequence							
	Wave/Twist in Tube Folio					Folio		Outside Dimensions					


H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G



NCR: Y	es / No				WORK ORDER NON-C	CONFO	RM	IANCE / UPD	DATE			
				•,						QA Closed:	Date	
Work Orde	r:				DISPOSITION				AGAINST DE	PARTMENT,	/PROCESS	
					Rework	]	S	kid-tube	Crosstube		Water Jet	Engineering
Part N	0				Scrap	]	Machining Small Fab			4	d. Eng. Coor.	Quality
					Use-as-is	│		oforming	Finishing	Rec/Stor	e/Packaging	Other
NCR N	0				Work Order Update	]	L	arge Fab	Composite	J	Supplier	
Root				Descri	ption of work order update	Initia	al	Acti	ion	Sign &		
Cause	Date	Step	Qty		or Non-conformance	Chief E	ng	Descri	iption	Date	Verification	QC Inspector
Doc/Data	_											
Equip/Tooling									•			
Operator		1				İ						
Material												
Setup							İ					
Other												
Process		Ì										
Supplier												
Training												
Unapproved		l				<u> </u>						
						AULT CA	ATEG					
Landin	g Gear	,			General 🏋 🏄		بمارد		1	7	<u></u>	!
1	Bending				Bend 🙏	Gra	in	14 15		Ovalized	<u> </u>	Pressure/Forced
	Centre No	ot Concei	ntric to C	)/S	_BOM/Route	Har	dware	e		Over/Under	<del> </del>	Temperature/Cure
	Cracks				Broken/Damaged	Insp	ectio	n Incomplete		Part Incorre	ct	Weld
	Crushed/	Crimped.			Burrs	Inst	ructio	ons Incomplete/L	Jnclear	Part Lost/M	issing	Wrong Stock Pulled
	Cuffs				Contamination	Ma	inter	nance		Part Moved		
	Heat Trea	it			Countersink	Mis	labele	ed		Positioned V	Wrong _	
	Inspection	n Strip in	Tube		Cut Too Short	Mis	read			Power Loss/	'Surge	Other
	Ripples in	Bend			Drill Holes	Offs	set		-			
Ī	Torque W	/aves in E	Extrusion		Drawing	Out	of Ca	alibration				
Ī	Turning S	equence			Finish	Out	of Se	equence				
Ī	Wave/Tw	ist in Tul	oe		Folio	Out	side (	Dimensions				

DQA: \_\_\_\_\_ Date: \_\_\_\_

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G



					DQA:	Date:
NCR:	Yes /	No	WC	ORK ORDER NON-CONFORMANCE / UPDATE		


										2 V 2	QA Closed:	Date			
Work Orde	or:		4.		<del></del>	DISPOSITION		AGAINST DEPARTMENT/PROCESS							
	•					Rework	]		Skid-tube	Crosstube	D	Water Jet	Engineering		
Part No. Scrap								·				d. Eng. Coor. re/Packaging	Quality Other		
NCR I	No.					Use-as-is Work Order Update		Thermoforming Finis  Large Fab Compo			Rec/Stol	Supplier	Other		
Root		Descriptio				ption of work order update	In	itial	A	ction	Sign &				
Cause		Date	Step	Qty		or Non-conformance	Chi	ef Eng	Des	cription	Date	Verification	QC Inspector		
Doc/Data															
Equip/Tooling															
Operator	Ш						į								
Material	Ш		}												
Setup	Ш														
Other	Ш														
Process															
Supplier	Ш														
Training		l													
Unapproved		· .	İ		<u> </u>						<u> </u>	<u> </u>			
							AULI	CATE	GORY						
Landing Gear General								<b>.</b>		<del>[</del>	Ovalized Pressure/Forced				
	$\overline{}$	Bending				Bend	$\vdash$	Grain		-	Ⅎ		Temperature/Cure		
	$\vdash$	Centre Not Concentric to O/S				BOM/Route		Hardwa	h		Over/Under tolerance Part Incorrect		Weld		
	$\vdash$	Cracks Crushed/Crimped.				Broken/Damaged	<b>⊢</b>	-	ion Incomplete	/Unalage	Part Lost/M	ļ	Wrong Stock Pulled		
	-		Crimped.	-		Burrs	-	Instructions Incomplete/Unclear			Part Moved	_			
	$\vdash$	Cuffs			ļ	Contamination	-	Maintenance   Mislabeled			-{				
	$\vdash$	Heat Trea		T. d	<u> </u>	Countersink	$\vdash$	Misrabe Misrea			Positioned Wrong Power Loss/Surge Other				
	-	Inspection	•	iube		Cut Too Short Drill Holes			u	<u>L</u>	Trower coss	Juige	Jouren		
	-	Ripples in		- :	<u> </u>	Drawing	Offset Out of Calibration								
	-	Torque W			" ·	<del>-1</del>	Out of Sequence								
]	1 1	Turning S	equence			Finish		Out of 3	sequence						

Outside Dimensions

Wave/Twist in Tube

Folio

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G



			,							DQA:	Date	•			
NCR:	es / No			x	WORK ORDER NON-C	100	NFORM	MANCE / UPI	DATE						
										QA Closed	Date				
Work Orde	nr.				DISPOSITION		AGAINST DEPARTMENT/PROCESS								
WOIK OIGE	=1.			<u> </u>	Rework		Skid-tube	Crosstube	7	Water Jet	Engineering				
Part N	lo				Scrap Use-as-is		Machining Small Fab Thermoforming Finishing			Prod. Eng. Coor.		Quality			
NCR N	No	<u></u>	······································		Work Order Update	Large Fab Composite			~ <del> </del>						
Root				Descri	ption of work order update		nitial	Act	ion	Sign &					
Cause	Date	Step	Qty		or Non-conformance	Ch	ief Eng	Descr	iption	Date	Verification	QC Inspector			
Doc/Data															
Equip/Tooling												·			
Operator															
Material					•										
Setup															
Other															
Process															
Supplier											1				
Training															
Unapproved			<u> </u>	<u></u>		<u> </u>				1	<u> </u>	_ <u></u>			
					F	AUI	T CATE	GORY							
Landing Gear General						_	1			7	Г	<b>-</b>			
	Bending				Bend		Grain Hardware			Ovalized	Ļ	Pressure/Forced			
	Centre	Not Conce	ntric to	O/S	BOM/Route	_				Over/Unde	<b>}</b>	Temperature/Cure			
	Cracks				Broken/Damaged		- 1	ion Incomplete	/  -	Part Incorr	<b>⊢</b>	Weld			
	Crushed/Crimped.				Burrs	<u> </u>	4	ictions Incomplete/Unclear.		Part Lost/N		Wrong Stock Pulled			
	Cuffs			<u></u>	Contamination	_	Maintenance			Part Moved					
	Heat Tr				Countersink		Mislabe		<u> </u>	Positioned		<b>_</b> .			
	Inspection Strip in Tube				Cut Too Short	$\vdash$	Misread			Power Loss	/Surge	Other			
	Ripples	in Bend			Drill Holes	1	Offset								

Out of Calibration

Out of Sequence

Outside Dimensions

Turning Sequence

Wave/Twist in Tube

Torque Waves in Extrusion

Drawing

Finish

Folio

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G